

Prepared by [REDACTED]

26 June 1969

1. throttle back from limit E.G.T.

NOTES ON EPR FLUCTUATIONS

2. Not on C

3.

1. Exists on U2C and U2R ~~II~~

2. Some Pilots squawk it or comment on it frequently. Some Pilots never mention it unless it is severe.

3. It seems to come in two varieties:

A. EPR needle movement only.

B. EPR, RPM and EGT all move and sometimes a noise or vibration in sync with needle movement is present.

4. On a given airplane - engine combination it is not always present.

5. Some people feel it is a function of FAT. Data doesn't substantiate this.

6. Most people say the aircraft is always smoother on the emergency fuel system. Very little factual data to substantiate this on the U2R. No data refuting it.

7. Reducing EGT and RPM slightly usually eliminates it.

8. Objective should be to eliminate what is seen, heard and felt by the Pilot.

9. It is assumed that the EPR is reflecting any airflow changes in the engine. More damping in the EPR instrumentation system should eliminate item 3A.

10. It appears that item 3B is an unstable airflow-fuel flow condition. If item 6 is true, it looks as though a change in fuel control sensing response could cure item 3B.

11. Items 9 and 10 would not necessarily cure the basic problem, but would obtain the objective and eliminate the problem.

12. This program can be accomplished without special instrumentation by trying various damping configurations and obtaining qualitative Pilot evaluation.

- 1. Garg correlates with F.A.T.*
- 2. All Bell data does not correlate*
- 3. may get out of it during climb (chuckey)*
- 4. pull back on power on a cold day - never achieve power E.P.R. limit.*
- 5. Engine in C does not operate the same*

1.220

1. where EGT lost slow cycling
2. EPR oscillates
EGT moves with it - & barely 2°m with it
3. 2 cases 3 weeks 053/061 had the problem
4° colder
Both flew the rest day w/ std. Temp.
no problem
4. Fuel control changed the characteristics between chunky's flt.
5. Apparently not a fuel control problem when in emergency
6. chunky ~~1/2~~₂ CPS
7. Amplitude decreases cycles ~~also~~ ^{increase} towards
8. as Amplitude increases then the engine responds more solidly.
9. ⁰⁵¹ 54, 55 Also std air syst. ~~was~~ tank in B & tank empty may have indicated
10. a problem.
11. Burner pressure (~~EGT~~) possibility.
12. Burner pressure
13. E.G.T.

1. Limit cycle control - best with burner pressure damping - ?
2. RPM - climb - reducing throttle to limit E.G.T. also reduces RPM - chunky -
3. possible change RPM. (No change P.W.)
4. why not have fuel control people here. change linkages
5. ~~Don't~~ RPM change not ~~known~~ known to any detail -
not very much - like only 1 case that it's been noted.
6. Back lash in the fuel control and throttle causes hunting.
7. the flt. test program should provide maximum instrumentation.
8. add other things to the list.
9. out of

There were 58 Reported
LAC cases of ~~0~~ EPR fluct.
of this

052 - ILT-823 on 5-17-68 The
first case of engine RFNS
26 - 6-28-68

053 clear

054 - [6] 4-19-68 - EPR 8/660

12 - 5-1-68 - pulsation

67- 2-12-69 ^{25X1A2a} [REDACTED]
75 3-18-69 [REDACTED]

055 OK no EPR

056 - 19/9-26-68/

057 2/ 8-2-68

51/8-22-68 70/min Beat

058 2/8-23-68

059/ 18/ 6-19-69/ Vibration on down cycle
EPR
Same case.

6-19-69

061/ 31 ~~fla~~ 6-16-69 flux & grinding

32 6-11-69 EGT/EPR
Grinding.

062/ 3/ 12-5-68/ at ^{below 40 m} 72.5, had
EGT & EPR

8/ 1-3-69 —

37/ 5-20-69 Grinding noise
louder on hi side of
EPR cycle - as alt.
increased freq to R CPS
then cut.

Should operate program
to define problem then
either
1. modify engine to fix
2. Tell pilot it's to be
expected, and accepted.

3. B. During program write
ups will continue to be made
in ~~the~~ the same ~~condition~~ condition.

we shall be requiring more ^{ELECT} power
on the program. and should
evaluate what other data we
can get for this program.

Dave

1. EPR flux could be averaged
2. Emergency doesn't have —
run a program to eliminate some
of the parameters, i.e. coolate
the fuel control (RPM) variations

try find problem in EM control

this is being expected
Clar

59 carries emergency fuel to perform EM.
than 665/165 — then the test
can be duplicated in emergency
to try to find the leak.

*one problem may be fixing
the problem*

25X1A5a2



*W. T. tests of the same
at creston*